

# 9. Studying the Positioning Accuracy

## 9.1. Causes of Error in Positioning Accuracy

Causes of error in the positioning accuracy include lead accuracy, axial clearance and axial rigidity of the feed screw system. Other important factors include thermal displacement from heat and orientation change of the guide system during traveling.